

Terminator DP/FAK-2LHT

Elbow Splice Kit for
Electrically Heated
TubeTrace® Bundles

INSTALLATION PROCEDURES



Terminator DP/FAK-2LHT Kit

The FAK 2LHT Elbow Splice Kit is designed to make a waterproof seal over the end of TubeTrace or ThermoTube where a 90° elbow is required. Review instructions prior to installation. Kit will make one splice connection. See separate instructions for details on splicing heating cables.

Receiving, Storing and Handling


1. Inspect materials for damage incurred during shipping.
2. Report damages to the carrier for settlement.
3. Identify parts against the packing list to ensure the proper type and quantity has been received.
4. Store in a dry location.

Terminator DP/FAK-2LHT Kit Contents



Item	Quantity	Description
1	1	Expediter Assembly: Flat Mount Base, Grommet, Threaded Grommet Compressor, and Support Cap with O-Ring
2	1	Junction Box Lid
3	1	Junction Box Base with O-Ring
4	1	Nut
5	1	Terminal Blocks with DIN Rail (Refer to terminal specifications for maximum allowable wire size)
6	1	Junction Box Cord
7	1	Heat Reflective Tape
8	3	RTV Sealant Tube
9	1	Glass Fiber Tape
10	1	90° Elbow Splice Cover (Top)
11	1	90° Elbow Splice Cover (Bottom)
12	1	Silicone Gasket
13	1	Self-Vulcanizing Tape
14	1	Fiberglass Rope, 13 mm x 366 cm (1/2" x 12')
15	1	Heavy Foil Tape, 44.5 mm (1.75") wide

Dimensions




	A mm (inch)	B mm (inch)	C mm (inch)
Terminator DP/FAK-2LHT	328 mm (12-7/8")	321 mm (12-5/8")	328 mm (12-7/8")


Installation Precautions

- To minimize the potential for arcing and ground-fault protection. The National Electrical Code (NEC) and Canadian Electrical Code (CEC) require ground-fault protection of equipment for each branch circuit supplying electric heat tracing.
- Installation must comply with Thermon requirements and be installed in accordance with the NEC, CEC, or any other applicable national and local codes.
- Component approvals and performance ratings are based on the use of Thermon specified parts only. User supplied power connection fittings must be listed or certified for intended use.
- De-energize all power sources before opening enclosure.
- Keep ends of heating cable and kit components dry before and during installation.
- Individuals installing these products are responsible for complying with all applicable safety and health guidelines. Proper personal protective equipment, or PPE, should be utilized during installation. Contact Thermon if you have any additional questions.


Tools Required



Terminator DP Certifications/Approvals




INSTALLATION PROCEDURES




1. Remove outer jacket and insulation from tubing bundle approximately 457 mm (18") from end of the tubing bundle.




Do not cut or damage the heat trace or sampling tube.
CAUTION (Found on TubeTrace SE/ME bundles)




2. Trim tubing to within 38 mm (1-1/2") of the end of the insulation. If self regulating heat trace proceed to step 3. For Zone-type heat trace continue with identification of bus connection on step 2a.



2a. Strip back bundle insulation 38 mm (1 1/2") to 76 mm (3") beyond bus connection indentation of each heat trace. If bus connection indentation is less than 305 mm (12")- 381 mm (15") from end of the heat tracing, proceed stripping the bundle insulation to the next indentation.



3. Make 90° elbow union connections (fitting provided by others). Test fitting for leaks before proceeding.




4. Wrap high temperature tubing with 1/2" fiberglass rope. Ensure 100% coverage to keep tubing and heat tracing from making contact.




5. Wrap with 1 pass of heavy foil tape (25% overlap).


DO NOT wrap heat trace with fiberglass rope.



6. Wrap with 3 passes of glass fiber tape (50% overlap).




7. Complete with 1 additional pass of heavy foil tape (25% overlap).




8. Add 1 additional pass of heavy foil tape (25% overlap) to cover heat trace.


Terminator DP/FAK-2LHT Kit




9. Wrap with 4 passes of glass fiber tape (50% overlap), or until fiber tape is equal to original bundle insulation thickness.




10. Wrap with 1 additional pass of heat reflective tape (50% overlap).




11. Cut splice cover top and splice cover bottom to match outside diameter of tubing bundle.



12. Mount expediter base with o-ring to splice cover bottom using (3) M5 mounting screws and lock washers. Punch out weep hole.




13. Install the Silicone Gasket (cut off excess). Apply RTV Sealant to both halves.



14. Assemble splice cover top, tubing bundle, and splice cover bottom together as shown. Snap together firmly. Inspect ends of tubing splice cover for snug fit. Apply additional RTV sealant where needed.



15. Apply self-vulcanizing tape around bundle jacket and work up over FAK ends.




16. Terminate heat tracing with appropriate PETK termination kit. Refer to PETK installation instructions (purchased separately) for details not addressed here.




17. Mount junction box on expediter making sure to align slots to properly orient junction box base.


INSTALLATION PROCEDURES



18. Install quick mount terminal blocks twist to position and tighten screws.



19. Complete system wiring as per wiring diagram.




In-Line Splice



20. Install junction box lid and twist hand tight. Insert screwdriver into ratchet slot located on side of junction box base to tighten. Use screwdriver ratchet on junction box lid. Lid will rotate 30°.



21. Lid latch mechanism fully engaged. To remove lid, repeat step 20 but in opposite direction.



22. Completed Terminator DP/FAK-2LHT assembly for Electrically Heated TubeTrace Bundles.

